




20_000046_03

Fig. 1: Fractured edge (example)

1 Fractured edge



When manufacturing metal cast parts (e.g. flywheels, pressure plates), the sprue is removed at a predetermined breaking point after the blank has been cast. This creates a fractured edge (1). This fractured edge (1) has no effect on the functioning or quality of the cast part. The component can be installed without any restrictions.



www.aftermarket.zf.com/serviceinformation